



Concorde Battery Corporation  
 2009 San Bernardino Road, West Covina, CA 91790  
 Phone (800) 757-0303 or (626) 813-1234  
 Email: customer-service@concordebattery.com  
<http://www.concordebattery.com>

An ISO 9001:2008 + AS9100 Certified Company

## ELIGIBILITY LIST

Revision: EL-85 (Revision Date: 2 October 2017)

(Contact the Concorde factory or consult website for latest revision number. Please contact Concorde for details prior to battery purchase.)

The item or technical data contained herein has been reviewed and approved for general release on the basis that it contains no export controlled information.

### FAA Approval Information

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
Agusta	A109C, A109E, A119, AW119 MKII (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR09360RC	RG-407; 6228 (Placard)	PMA Supplement No. 57 Issued 6/16/03 Rev. 1/15/10 TSO Authorized: RG-407
Agusta	A119, AW119 MKII (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR04007AT	RG-427 ; 6228 (Placard)	PMA Supplement No. 104 Issued 9/16/13 TSO Authorized: RG-427
Agusta	A109A, A109C, A109E (Replacing Ni-Cd battery)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	PMA Supplement No. 62 Issued 10/30/03 Rev. 4/12/2017 TSO Authorized: RG-407
Agusta	AB139, AW139 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR03072NY	RG-380E/44L or RG-380E/60L; RG-407 (Auxiliary); 6228 (Placard)	PMA Supplement No. 113 Issued 12/16/16 TSO Authorized: RG-407; RG-380E/44L, /60L
Airbus Group	TBM 700 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SA00775LA	RG-380E/44; 8481 (Placard)	PMA Supplement No. 39 Issued 4/23/99 TSO Authorized:RG-380E/44
Airbus Helicopters	AS350 B, BA, B1, B2, B3, D (Replacing P/N 151CH-1 Ni-Cd battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-350	PMA Supplement No. 52 Issued 2/18/03 TSO Authorized: RG-350
Airbus Helicopters	AS350 B, B1, B2, BA, C, D, D1 (To replace P/N 1606-1 Ni-Cd battery)	Falcon Crest (800) 833-5422	STC# SR09185RC	RG-355	PMA Supplement No. 35 Issued 3/06/98 TSO Authorized: RG-355
Airbus Helicopters	AS355 E, F, F1, F2, N (To replace P/N 1606-1 Ni-Cd battery)	Falcon Crest (800) 833-5422	STC# SR09186RC	RG-355	PMA Supplement No. 35 Issued 3/06/98 TSO Authorized: RG-355
Airbus Helicopters	BK-117-A-1, -A-3, -A-4, -B-1, -B-2, -C-1 (Replacing Ni-Cd battery)	Falcon Crest (800) 833-5422	STC & STA# SR09034RC	RG-390E	PMA Supplement No. 21 Issued 11/15/95 TSO Authorized: RG-390E
Airbus Helicopters	BO-105C & BO-105S (Replacing Ni-Cd battery)	Falcon Crest (800) 833-5422	STC# SR09016RC	RG-390E	PMA Supplement No. 21 Issued 11/15/95 TSO Authorized: RG-390E
Airbus Helicopters	EC130B4, EC130ST2 (Replacing P/N 151CH-1 Ni-Cd battery)	Rotorcraft Support (818) 997-7667	STC# SR02073LA	RG-350	PMA Supplement No. 88 Issued 7/15/09 TSO Authorized: RG-350
Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC225LP (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR02588LA	RG-332-1 or RG-332-2	PMA Supplement No. 114 Issued 11/14/16 TSO Authorized: RG-332-1, -2
American Champion	7ECA, 7GCAA, 7KCAB, 8GCBC, 8KCAB	Amer. Champion (262) 534-6315	TC# A-759 TC# A-21CE	RG-25	PMA Supplement No. 31 Issued 6/03/97
Aviat Inc.	A-1A, A-1B, S-2C	Aviat Inc. (307) 885-3151	TC# A22NM TC# A8SO	RG-25	PMA Supplement No. 42 Issued 8/06/01

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
Aviat Inc.	A-1, S-1S, S-1T, S-2, S-2A, S-2S, S-2B	Aviat Inc. (307) 885-3151	TC# A22NM TC# A8SO	RG-25	PMA Supplement No. 18 Issued 8/02/95
Avions de Transport Regional (ATR)	ATR42 Series; ATR72 Series (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST03930AT	RG-380E/44; RG-42 (Emergency) 7945 (Dummy TS); 6716 (Placard)	PMA Supplement No. 97 Issued 9/28/11 TSO Authorized: RG-42; RG-380E/44
Beechcraft	MU-300-10, 400, 400A (Replacing Ni-Cd battery)	Textron Aviation (800) 256-6012	STC# SA2494SO	RG-380E/40B	PMA Supplement No. 22 Issued 1/23/96 TSO Authorized: RG-380E/40B
Beechcraft	A200CT (Military), RC-12K	Wilco (800) 767-7593	FAA Design Approval	TS-C6 (P/N 5-0125, Kit, TS, TS-C6)	PMA Supplement No. 70 Issued 5/28/04
Beechcraft	65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200, 300, MU-300-10, 400, 400T (T-1A) (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
Beechcraft	65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU- 21A, RG-21D, U-21G, RU-21H), 65-A90-4 (RU- 21E, RU-21H), B90, C90, 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), E90, H90 (T-44A), C90A, F90, 99, 99A, 99A (FACH), 100, A99, A99A, A100 (U-21F), B99, A100A, B100, C99, 200 (A100-1(U-21J)), A200C (UC-12B), 200C, B200, B200C (C-12F, UC-12F, UC-12M, C-12R), A200 (C-12A, C-12C), 200T, 200CT, A200CT (C-12D, C-12F, FWC-12D, RC-12D, RC-12F, RC-12G, RC-12H, RC-12K, RC-12P, RC-12Q), B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900D (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SA01260WI	Options as follows: RG-380E/40L RG-380E/40K RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	PMA Supplement No. 73 Issued 8/11/04 TSO Authorized: RG-380E/40L, /40K, /44L, /44K, /60L, /60K
Beechcraft	Kingair 65-90, 65-A90, 65-A90-1 (Military U-21A, RU21A, RU21D, JU21A, U-21G, RU21H/GRV), 65-A90-4 (Military RU21E, RU21H/GRV & IV), B90, C90, 65-A90-2 (Military RU-21B), 65-A90-3 (Military RU-21C), E90, H90, (Military T-44A), C90A, F90, 99 & 99A, (Military 99A), 100, A99, A99A, A100 (Military U-21F), B99, A100A, B100, C99, 200, A200C, (Military UC-12), 200C, B200, B200C, (Military C-12F, UC-12F & UC-12M), A200 (Military C-12A, C-12C), 200T, 200CT, A200CT (Military C-12D, FWC-12D, RC-12D, C-12F, RC- 12G, RC-12H), B200CT, B200T, 200T, A100-1 (Military U-21J), A200CT (Military RC-12K), 1900, 1900C, 1900D, 300, 300LW, B300, B300C, (S/N: FM-1 & subsequent, FN-1 & subsequent) (Replacing Ni-Cd battery)	Wilco (800) 767-7593	STC# SA00741WI	Options as follows: RG-380E/40K RG-380E/44K RG-380E/60K	PMA Supplement No. 41 Issued 8/16/01 Rev. 8/13/02 TSO Authorized: RG-380E/40K, /44K, /60K
Beechcraft	200, 300, & B300 Series (Replacing Ni-Cd battery)	Textron Aviation (800) 256-6012	STC# SA2699SO	RG-380E/40B	PMA Supplement No. 22 Issued 1/23/96 TSO Authorized: RG-380E/40B
Beechcraft	400A (S/N RK-98 and after) (Replacing Beechcraft part no.)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40L	PMA Supplement No. 49 Issued 1/23/03 TSO Authorized: RG-380E/40L
Beechcraft	Hawker 1000 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00640LA	RG-380E/60K; 9861 (Tray, Temp); Misc. Hardware	PMA Supplement No. 39 Issued 4/23/99 PMA Supplement No. 105 Issued 3/13/14 TSO Authorized: RG-380E/60K
Beechcraft	BH.125 Series 1A, 1A/522, 1A/R-522, 1A/S-522; Series 3A, 3A/R, 3A/RA, BH.125 400A, 600A, HS.125 600A, 700A, BAe 125-800A; Hawker 800, 800XP (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00415LA	RG-390E	PMA Supplement No. 39 Issued 4/23/99 TSO Authorized: RG-390E

<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>Beechcraft</b>	DH.125 Series, HS.125 Series, BH.125 Series (Replacing Ni-Cd emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01223WI	RG-125	PMA Supplement No. 65 Issued 1/30/04 TSO Authorized: RG-125
<b>Beechcraft</b>	400A Series (S/N's RK-98 and after) (Replacing 38Ah lead-acid battery)	Textron Aviation (800) 256-6012	STC# ST02506AT	Options as follows: RG-380E/44, RG-380E/44L, RG-380E/60L	PMA Supplement No. 44 Issued 6/13/02 TSO Authorized: RG-380E/44, /44L, /60L
<b>Beechcraft</b>	35, A35, B35, C35, 35R, D35, E35, F35, G35, 35, J35, K35, M35, 35-33, N35, 35-A33, 35-B33, P35, S35, 35-C33, E-33, F-33, G-33, V35, V35A, 35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C, A36TC, B36TC, 23, A23, A23A, A23-19, A23-24, A24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R	Wilco (800) 767-7593	STC# SA00638WI	RG-35A (12V) RG-35AXC (12V) RG24-16 (24V)	PMA Supplement No. 37 Issued 6/22/98 Rev. 6/29/98 PMA Supplement No. 82 Issued 7/18/07 TSO Authorized: RG24-16
<b>B-N Group Ltd.</b>	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN- 2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN- 2B-27, BN-2T, BN-2T-4R	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E	PMA Supplement No. 34 Issued 11/18/97 TSO Authorized: RG-390E
<b>Bell</b>	206A & 206B (Replacing Ni-Cd battery)	Falcon Crest Av. (800) 833-5422	STC & STA# SR09054RC	RG-206	PMA Supplement No. 23 Issued 4/04/96 TSO Authorized: RG-206
<b>Bell</b>	212 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/6/92 TSO Authorized: RG-380E/40B, /44
<b>Bell</b>	214ST (Replacing Ni-Cd battery) (Battery available through STC holder)	Falcon Crest Av. (800) 833-5422	STC# SR09225RC	RG-214	PMA Supplement No. 45, Issued 10/22/02
<b>Bell</b>	222U (Replacing Ni-Cd battery)	Falcon Crest Av. (800) 833-5422	STC# SR09142RC	RG-380E/44	PMA Supplement No. 30 Issued 5/18/97 TSO Authorized: RG-380E/44
<b>Bell</b>	212, 412, 412EP (Replacing Ni-Cd battery)	Falcon Crest Av. (800) 833-5422	STC & STA# SR09053RC	RG-380E/44	PMA Supplement No. 23 Issued 4/04/96 TSO Authorized: RG-380E/44
<b>Bell</b>	206L-1, 206L-3, 206L-4 (Replacing Ni-Cd battery)	Falcon Crest Av. (800) 833-5422	STC & STA# SR09069RC	RG-222	PMA Supplement No. 25 Issued 6/07/96 TSO Authorized: RG-222
<b>Bell</b>	222, 222B (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR04212AT	RG-222; 6716 (Placard)	PMA Supplement No. 110 Issued 9/22/15 TSO Authorized: RG-222
<b>Bell</b>	407 (Replacing Ni-Cd battery) (Battery available through STC holder)	Falcon Crest Av. (800) 833-5422	STC# SR09359RC	RG-407A1	PMA Supplement No. 58, Issued 6/19/03
<b>Bell</b>	407, 427, 430 (Replacing Ni-Cd battery)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407 or RG-427 (RG-427 – Bell 407, 427 only)	PMA Supplement No. 62 Issued 10/30/03 Rev. 4/12/2017 TSO Authorized: RG-407, RG-427
<b>Boeing</b>	737-300, -400, -500 Series (Replacing Ni-Cd Battery)	Concorde Battery (800) 757-0303	STC# ST04373AT	RG-380E/40D	PMA Supplement No. 118 Issued 8/23/2017 TSO Authorized: RG-380E/40D
<b>Boeing</b>	737-600, -700, -800, -900 Series (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST03932AT	RG-380E/60B 9507 (Dummy Temp. Plug); 7053 (Bolt)	PMA Supplement No. 96 Issued 9/28/11 PMA Supplement No. 115 Issued 12/12/16 TSO Authorized: RG-380E/60B
<b>Bombardier Inc.</b>	CL-600-2B16, -2B19, -2C10, -2D24 (Replacing Ni-Cd battery)	Concorde Battery (800) 756-0303	STC# ST01646WI	RG-223; RG-380E/44L (APU); 5-0166 (Kit, TS, TS-C11A); 5-0283 (Kit, TS, TS-C11B)	PMA Supplement No. 99 Issued 1/13/12 Rev.1/16/15 TSO Authorized: RG-223; RG-380E/44L
<b>Bombardier Inc.</b>	DHC-8-100, -200, -300 (Replacing Ni-Cd battery)	Concorde Battery (800) 756-0303	STC# ST01643WI	RG-380E/44 or RG-380E/60L; 5-0290 (Plug, Dummy TS); 6299 (Placard)	PMA Supplement No. 95 Issued 9/09/11 Rev. 9/23/16 TSO Authorized: RG-380E/44, /60L

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
British Aerospace	Jetstream 3101 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SA2994SO	RG-390E	PMA Supplement No. 16 Issued 5/18/92 TSO Authorized: RG-390E
British Aerospace	Jetstream 3201 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SA2995SO	RG-390E	PMA Supplement No. 16 Issued 5/18/92 TSO Authorized: RG-390E
British Aerospace	Jetstream 3201 (S/N: 790 – 9999) (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00342LA	RG-380E/40B or RG-380E/44	PMA Supplement No. 32 Issued 6/11/97 TSO Authorized: RG-380E/40B, /44
Cessna	<p align="center"><b>SINGLE ENGINE MODELS</b></p> <p>120, 140, 140A, 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 175, 175A, 175B, 175C, P172D, R172E (USAF T-41B)(USAF T41C&amp;D), R172F(USAF T-41D), R172G ((USAF T-41C &amp; T-41D), R172H (USAF T-41D), R172J, R172K, 172RG, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, R182, TR182, 182S, 182T, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 188, 188A, A188, A188A, 188B, A188B, T188C, 190, 195, 195A, 195B, 206, 206H, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, T206H, 207/T207, 207A/T207A, 305B, 305E, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, T210H, 210H, T210J, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 305B, 305E (Military TO-1D, O-1D, O-1F), 337, 337A (USAF O2B), 337B, 337C, 337D, 337E, 337F, 337G, 337H/T337H, T337B, T337C, T337D, T337E, T337F, T337G, M337B (USAF O2A), P337H, T337H-SP.</p> <p align="center"><b>TWIN ENGINE MODELS</b></p> <p>T303, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, E310I, E310J, 310J, 310J-1, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F, 335, 340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 404, 411, 411A, 414, 414A, 421, 421A, 421B, 421C</p>	Concorde Battery (800) 757-0303	STC# SA01118WI <sup>3</sup>	RG-25 or RG-25XC Replaces Cessna P/N 0511319-1  RG-35A or RG-35AXC Replaces Cessna P/N 0712605-1 or P/N 0712604-1 or P/N 0311053  RG24-16 Replaces Cessna P/N C614001-0106  RG24-15M Replaces Cessna P/N C614002-0102  RG24-10 Replaces Cessna P/N C614001-0105  RG24-20 Replaces Cessna P/N 5018200-201 & REBAT P/N R2425	PMA Supplement No. 83 Issued 9/20/07 Rev. 10/21/09 TSO Authorized: RG24-15M, RG24-16

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
Cessna	120, 140, 140A, 170, 170A, 170B, 172 thru 172Q, 172R, 172S, 210, 210A thru 210R, T210F thru T210R, P210N, P210R, 210-5, 210-5A, 175, 175A, 175B, 175C, 172RG, P172D, R172E, R172F thru R172K, 177, 177A, 177B, 177RG, 180, 180A thru 180K, 185, 185A thru 185E, A185E, A185F, 188, 188A, 188B, A188, A188A, A188B, T188C, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C thru P206E/TP206E, U206C/TU206C thru U206G/TU206G, 206H, 207, 207A, T207, T207A, 305B, 305E, 337, 337A thru 337H, T337B thru T337H, M337B, P337H, T337H-SP, 150, 150A thru 150M, A150K thru A150M, 152, A152	Wilco (800) 767-7593	STC# SA00897WI <sup>3</sup>	RG-25 or RG25XC Replaces Cessna P/N 0511319-1  RG-35A or RG35AXC Replaces Cessna P/N 0712605-1  RG24-11 or RG24-15 Replaces Cessna P/N C614002-0102  RG24-11M or RG24-15M Replaces Cessna P/N C614001-0106	PMA Supplement No. 43 Issued 9/04/01 TSO Authorized: RG24-15, RG24-15M
Cessna	210 (S/N: 21059503 & on), T210	Wilco (800) 767-7593	STC# SA2558CK	RG24-11M	PMA Supplement No. 14 Issued 2/07/91
Cessna	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182/TR182, 182R/T182 (182 through S/N: 18265965 except: 18263479)	Wilco (800) 767-7593	STC# SA00753WI	RG-35A RG-35AXC	PMA Supplement No. 41 Issued 8/16/01 Rev. 8/13/02
Cessna	182 Series (S/N:18263479, 18265966 and up), R182 and TR182 Series (S/N: R18200001 and up)	Wilco (800) 767-7593	STC# SA00753WI	RG24-15	PMA Supplement No. 41 Issued 8/16/01 Rev. 8/13/02 TSO Authorized: RG24-15
Cessna	425 (Conquest I) (Replacing Ni-Cd battery)	Wilco (800) 767-7593	STC# SA2435CE	RG-380E/44	PMA Supplement No. 14 Issued 2/07/91 TSO Authorized: RG-380E/44
Cessna	441 (Conquest II) (Replacing Ni-Cd battery)	Wilco (800) 767-7593	STC# SA2496CE	RG-380E/44	PMA Supplement No. 14 Issued 2/07/91 TSO Authorized: RG-380E/44
Cessna	550 (Citation II) Series (Replacing Ni-Cd batteries)	Concorde Battery (800) 757-0303	STC# ST01639LA	RG-131	TSO Authorized: RG-131
Cessna	510 (Replacing Concorde P/N RG-390E)	Concorde Battery (800) 757-0303	STC# SA02653LA	RG-390E/30	PMA Supplement No. 117 Issued 8/22/17 TSO Authorized: RG-390E/30
Cessna	(Caravan) 208, 425, 441 ; (Citation II) 500, 501, 550, 551 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
Cessna	680 Sovereign (Replacing Ni-Cd batteries)	Concorde Battery (800) 756-0303	STC# ST04366AT	RG-380E/53L or RG-380E/60L 5-0121 (Kit, TS, TS-C1B) 6424 (Screw, Cap, Socket Head – Inc. in 5-0121 Kit, TS, TS-C1B)	PMA Supplement No. 116 Issued 5/30/17 TSO Authorized: RG-380E/53L, /60L
Cirrus	SR20, SR22	Concorde Battery (800) 757-0303	STC# SA01304WI	RG24-11M or RG24-15M	PMA Supplement No. 76 Issued 2/18/05 TSO Authorized: RG24-15M

<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>Dassault</b>	Falcon 7X, 10, 900EX, 2000, 2000Ex Fan Jet Falcon Fan Jet Falcon Series C, D, E, F, G Mystere-Falcon 50, 200, 900 Mystere-Falcon 20-C5, -D5, -E5, -F5 (Replacing original battery airframe connector – Several commercial designations listed on the Type Certificates as derivatives of approved models & all commercial designations are eligible under this STC).	Concorde Battery (800) 757-0303	STC# ST04273AT	4000	PMA Supplement No. 111 Issued 8/19/16
<b>Dassault</b>	Falcon 7X (Replacing original 25Ah lead-acid battery)	Concorde Battery (800) 757-0303	STC# ST04185AT	RG-390E/KH; 5-0312 (Kit, HCU, HCU-7X); 8214 (Hold down bar, 7X)	PMA Supp.108 Issued 6/05/15 TSO Authorized: RG-390E/KH; HCU-7X
<b>Dassault</b>	Falcon 10 (Replacing 22Ah Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00774LA	RG-390E; 9899 (TS Tray)	PMA Supplement No. 39 Issued 4/23/99 TSO Authorized: RG-390E
<b>Dassault</b>	Falcon 20 Series, C, D, E, F (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>Dassault</b>	Falcon 50, 50EX, 900, 900EX, 900DX, 2000, 2000EX (Replacing Ni-Cd or lead-acid emergency battery)	Concorde Battery (800) 757-0303	STC# ST01571WI	RG-128 Series	PMA Supplement No. 90 Issued 2/12/10 TSO Authorized: RG-128 Series
<b>Dassault</b>	MF 50 (Replacing 23Ah Ni-Cd battery) (Battery Mod. - Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	PMA Supplement No. 51 Issued 2/21/03 TSO Authorized: RG-390E/LS
<b>Dassault</b>	MF900, F900EX (Replacing 23Ah Ni-Cd battery) (Battery Mod. - Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	PMA Supplement No. 51 Issued 2/21/03 TSO Authorized: RG-390E/LS
<b>Dassault</b>	Falcon 2000 (Replacing 36Ah Ni-Cd battery) (Battery Mod. - Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44LS	PMA Supplement No. 51 Issued 2/21/03 TSO Authorized: RG-380E/44LS
<b>de Havilland Aircraft</b>	See Bombardier Inc. & Viking Air Ltd				
<b>Dornier</b>	328-100 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00732DE	RG-380E/44LS	PMA Supplement No. 98 Issued 11/10/11 TSO Authorized: RG-380E/44LS
<b>EADS CASA</b>	C-212-CB, -CC, -CD, -CE, -CF, -DF, -DE (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST04178AT	Options as follows: RG-380E/40B or RG-380E/44 or RG-380E/46; RG-616 (Auxiliary); Install Kit: 7766 (Connector) & 7767 (Strain Relief); 6228 (Placard)	PMA Supplement No. 107 Issued 2/09/14 TSO Authorized: RG-616; RG-380E/40B, /44, /46
<b>EADS CASA</b>	CN-235, CN-235-100, CN-235-200, CN-235-300, C295 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST04211AT	RG-235 7906 (Dummy TS); 6228 (Placard)	PMA Supplement No. 109 Issued 9/21/15 TSO Authorized: RG-235

<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>Embraer</b>	EMB-110P1, EMB-110P2 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>Embraer</b>	EMB-120, EMB-120RT, EMB-120ER, EMB-120FC, EMB-120QC (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST02600LA	Options as follows: RG-380E/40B or RG-380E/44 or RG-380E/46; 6746 (Placards 6746-1, -2)	PMA Supplement No. 112 Issued 8/22/16 TSO Authorized: RG-380E/40B, /44, /46
<b>Embraer</b>	135BJ, 135ER, 135LR, 135KE, 135KL, 145, 145EP, 145ER, 145LR, 145MP 145MR, 145XR (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST01520WI	RG-442; 5-0124 (Kit, TS, TS-C4)	PMA Supplement No. 86 Issued 3/09/09 TSO Authorized: RG-442
<b>Embraer</b>	EMB-500 (Phenom 100) (Replacing lead-acid battery)	Concorde Battery (800) 757-0303	STC# SA01633WI	RG-390E	PMA Supplement No. 94 Issued 9/09/11 TSO Authorized: RG-390E
<b>Embraer</b>	EMB-505 (Phenom 300) (Replacing lead-acid battery)	Concorde Battery (800) 757-0303	STC# SA01703WI	RG-380E/44; RG-390E (Auxiliary) 7000 (Spacer – Use with RG-390E)	PMA Supplement No. 102 Issued 12/14/12 TSO Authorized: RG-390E; RG-380E/44
<b>Enstrom Helicopter</b>	F-28F & 280FX	Enstrom Helicopter (906) 863-1200	TC# H1CE, Rev. 20, Rev. A	RG-35A (12V) RG24-11M (24V)	PMA Supplement No. 23 Issued 4/04/96
<b>Garlick Helicopters</b>	Bell UH-1F, UH-1P, TH-1F (Replacing Ni-Cd battery)	Tamarack Heli. (406) 777-1044	(Omitted pending STC number correction)	RG-390E	PMA Supplement No. 53 Issued 3/26/03 TSO Authorized: RG-390E
<b>Globe</b>	GC-1A, GC-1B	Swift Museum (423) 745-9547	TC# A-766	RG-35A	PMA Supplement No. 63 Issued 10/30/03
<b>Gulfstream</b>	Galaxy/Gulfstream 200	Gulfstream Aero. (214) 902-7770	STC# ST09945SC	5-0122 (Kit, Temp. Sensor TS-C2A)	PMA Supplement No. 87 Issued 4/13/09
<b>Gulfstream</b>	(Gulfstream I) G-159 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>Gulfstream</b>	GII (G-1159), GIII (G-1159A), GII (G-1159B) (DC System) (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00773LA	RG-380E/44	PMA Supplement No. 40 Issued 4/30/99 TSO Authorized: RG-380E/44
<b>Gulfstream</b>	GIII (G-1159A)(s/n 357, 402 & up), GIV (AC System) (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00544LA	RG-380E/44; 9713 (Adaptor, Charger)	PMA Supplement No. 38 Issued 11/02/98 TSO Authorized: RG-380E/44
<b>Israel Aircraft</b>	1121, 1121A, 1121B (Jet Commander) 1123, 1124 (Westwind) (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>JetProp LLC</b>	Piper PA-46-310P, PA-46-350P (Included as part of STC for turbine conversion)	Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-46	PMA Supplement No. 54 Issued 4/29/03
<b>JetProp LLC</b>	Piper PA-46-310P, PA-46-350P (Higher Capacity Replacement) (Included as part of STC for turbine conversion)	Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-49	PMA Supplement No. 54 Issued 4/29/03 TSO Authorized: RG-49
<b>Kaman Aerospace</b>	K1200	Concorde Battery (800) 757-0303	TC# TR7BO	RG-380E/40B	PMA Supplement No. 26 Issued 6/21/96 TSO Authorized: RG-380E/40B

<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>Learjet</b>	23, 24, 25, 28, 29, 35, 36, 55 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>Learjet</b>	40, 45 (Replacing Concorde Part No. RG-443) (STC for emergency battery only)	Global Aviation (316) 425-0998	STC# ST01639WI	RG-145-2	PMA Supplement No. 93 Issued 9/09/11 TSO Authorized: RG-145-2
<b>Learjet</b>	45 (Replacing lead-acid emergency) (STC for emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01173WI	RG-443	PMA Supplement No. 59 Issued 6/23/03
<b>M-7 Aerospace</b>	SA226-AT, SA227-AT, SA226-T, SA227-CC, -DC (RG-390ES replaces M-7 P/N FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	PMA Supplement No. 60 Issued 6/25/03 TSO Authorized: RG-390ES
<b>M-7 Aerospace</b>	Fairchild SA227AC, SA227BC (RG-390ES replaces M-7 P/N FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	PMA Supplement No. 17 Issued 6/27/95 TSO Authorized: RG-390ES
<b>M-7 Aerospace</b>	Fairchild SA226-T, SA226-T(B), SA227-TT (Replaces P/N RG-91A which replaces M-7 P/N FASRG91STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-91	PMA Supplement No. 69 Issued 5/17/04
<b>Maule</b>	M-4-210, M-4-220, M-4-180, M-5-180, M-5-210, M-5-220, M-5-235, M-5-210TC, M-5- 200, M-6-180, M-6-235, M-7-235, M-7-235A, M-7- 235B, M-7-235C, M-7-260, M-7-260C, M-8-235, MT-7-235, MT-7-260, MX-7-160, MX-7-160C, MX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MX-7-180AC, MX-7-235, MXT-7-160, MXT-7-180, MXT-7-180A	Maule Aerospace (229) 985-2045	FAA Design Approval	RG-35A RG-35AXC	PMA Supplement No. 64 Issued 1/06/04
<b>MD Helicopter</b>	MD369, 369A, 369D, 369F, 369FF, 369H, 369HM, 369HS, 369HE, 369E and 500N (Replacing Ni-Cd battery)	Advanced Power (909) 599-7319	STC# SR00716SE	RG-500; CBP-3349-2W (Connector Part No. 4002); 9542 (Adaptor)	PMA Supplement No. 47 Issued 12/02/02 TSO Authorized: RG-500
<b>MD Helicopter</b>	MD369D, 369E, 369F, 369FF, 500N, 600N (Replacing lead-acid or Ni-Cd battery)	Concorde Battery (800) 757-0303	STC SR00846DE	RG-624; CBP-3349-2W (Connector Part No. 4002); 8481 (Placard)	TSO Authorized: RG-624
<b>MD Helicopter</b>	600N (Replacing Ni-Cd battery with the connector receptacle on right side of battery container – Used for most 600N models)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-1; CBP-3349-2W (Connector Part No. 4002); 9542 (Adaptor)	PMA Supplement No. 67 Issued 2/06/04 TSO Authorized: RG-600-1
<b>MD Helicopter</b>	600N (Replacing Ni-Cd battery with the connector receptacle on left side of battery container)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-2; CBP-3349-2W (Connector Part No. 4002); 9542 (Adaptor)	PMA Supplement No. 67 Issued 2/06/04 TSO Authorized: RG-600-2



<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>MD Helicopter</b>	MD-900 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR03895AT	RG-407; 5-0349 (Elbow Coupling Assembly) (Assembly includes 8003, (Elbow, Vent Adaptor), & 8086 (Coupling))	PMA Supplement No. 92 Issued 9/09/11 TSO Authorized: RG-407
<b>Mitsubishi</b>	MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, 30, 35, 36, 36A, 40, 60, MU-300-1, -1A (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
<b>Mitsubishi</b>	YS-11A Series (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SA2795SO	RG-390E	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-390E
<b>Mooney</b>	M20, M20A, M20B, -20C, -20D, -20E, -20F, M20G, M20J (S/N 24-0001 to 24-2999), M20K (S/N 25-0001 to 25-0999)	Concorde Battery (800) 757-0303	Identicality per 14 CFR § 21.303	RG-35A (Replacing R-33) or RG-35AXC (Replacing R-35)	PMA Supplement No. 77 Issued 3/01/05
<b>Mooney</b>	M20J, M20K, M20L, M20M, M20R, M20S, M20TN (24V models) (Please note certain 24V models may have fitment issues when attempting to install part no. RG24-15. Please contact Concorde for details).	Concorde Battery (800) 757-0303	Identicality per 14 CFR § 21.303	RG24-11M (Replacing manifold battery) or RG24-15 (24V)	PMA Supplement No. 84 Issued 2/01/08
<b>Piaggio Aero Industries SpA</b>	P180	Concorde Battery (800) 757-0303	STC# SA01653LA	RG-380E/40L; 5-0242 (Kit, TS, TS-C6A)	PMA Supplement No. 74 Issued 9/27/04 TSO Authorized: RG-380E/40L
<b>Pilatus</b>	PC-12 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# ST00776LA	RG-380E/44	PMA Supplement No. 39 Issued 4/30/99 TSO Authorized: RG-380E/44

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
Piper	PA-12, PA-12S, PA-18, PA-18 "105" (Special), PA-18 "125" (Army L-21B), PA-18 "135" (Army L-21B), PA-18 "150", PA-18A, PA-18A "135", PA-18A "150", PA-18S, PA-18S "105", PA-18S "125", PA-18S "135", PA-18S "150", PA-18AS "125", PA-18AS "135", PA-19 (Army L-18C), PA-19S, PA-20, PA-20 "115", PA-20 "135", PA-20S, PA-20S "115", PA-20S "135", PA-22, PA-22-108, PA-22-135, PA-22-150, PA-22-160, PA-22S-135, PA-22S-150, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250 (Navy UO-1), PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-30, PA-31, PA-31-300, PA-31-350 & T-1020, PA-31-325 C/R, PA-32-260, PA-32-300, PA-32-301, PA-32-301T, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301, PA-32R-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-36-285, PA-36-300, PA-36-375, PA-36-285, PA-38-112, PA-39, PA-40, PA-44-180, PA-44-180T TURBO, PA-46-310P, PA-46-350P, PA-60-600, PA-60-601, PA-60-601P, PA-60-602P, PA-60-700P, PA-400	Concorde Battery (800) 757-0303	STC# SA01147WI <sup>3</sup>	RG-25 ; RG-25XC Replaces original battery P/N 450-030  RG-25 - Replaces original battery P/N 450-022  RG-35A; RG-35AXC Replaces original battery P/N 450-035  RG24-11 ; RG24-15 ; RG24-16 Replaces original battery P/N 450-027 or 450-032  RG24-11M ; RG24-15M Replaces original battery P/N 450-101  RG24-20 - Replaces original battery P/N 450-028, 450-031 or 450-029 (Note – Install. kit may be required)  PMA reference only : 5-0161 (Installation kit) ; 9771 (Hold down bar) ; 8798 (Spacer)	PMA Supplement No. 50 Issued 3/7/03 Rev. 2/10/15 PMA Supplement No. 103 Issued 2/26/13 TSO Authorized: RG24-15, RG24-15M, RG24-16
Piper	PA-12, PA-12S, PA-18, PA-19 (Army L-18C), PA-18 "125" (Army L-18A) , PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18 "105", PA-18S, PA-19S, PA-18S "125", PA-18S "135", PA-18AS "125", PA-18AS "135", PA-18S "105", PA-18 "150", PA-18A "150", PA-18S "150", PA-18A, PA-18A "135", PA-18A "150"; PA-20, PA-20 "115", PA-20S, PA-20S "115", PA-20S "135", PA-20 "135", PA-22, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA-22-108, PA-24, PA-24-250, PA-24-400, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-23, PA-23, PA-23-160, PA-23-250, (Navy UO-1), PA-28-160, PA-28-150, PA-28-180, PA-28S-160, PA-28S-180, PA-28-235, PA-28-140, PA-28R-200, PA-28-151, PA-28-181, PA-28-161, PA-28R-201, PA-28R-201T, PA-28-236, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-38-112, PA-36-285, PA-36-300, PA-36-375, PA-46-310P, PA-46-350P	Wilco (800) 767-7593	STC# SA00954WI <sup>3</sup>	RG-25 or RG-25XC Replaces original battery P/N 450-030  RG-35A or RG-35AXC Replaces original battery P/N 450-035  RG24-11 or RG24-15 Replaces original Battery P/N 450-032  RG24-11M or RG24-15M Replaces original battery P/N 450-101  RG24-20 Replaces original battery P/N 450-031	PMA Supplement No. 43 Issued 9/04/01 TSO Authorized: RG24-15, RG24-15M

Manufacturer	Model & Certificate Notes <sup>8</sup>	Certificate Holder	Certificate Number (or FAA Design Approval)	Concorde Part Number <sup>7</sup>	FAA Approval Type
Piper	PA-23 Apache, PA-23-160, PA-23-250 (Navy UO-1), PA-23-235, PA-E-23-250 Aztec, PA-23-250, PA-31 Navajo, PA-31-300 Navajo, PA-31-350 Chieftan & T-1020, PA-31-325 Navajo C/R, PA-44-180 Seminole, PA-44-180T Turbo Seminole, PA-30 Twin Comanche, PA-39 Twin Comanche, PA-40 Twin Comanche, PA-34-200 Seneca, PA-34-200T Seneca II, PA-34-220T Seneca III, IV, V	Wilco (800) 767-7593	STC# SA00954WI <sup>3</sup>	RG-25 or RG-25XC Replaces P/N 450-030  RG-35A or RG-35AXC Replaces P/N 450-035  RG24-11 or RG24-15 Replaces P/N 450-032  RG24-11M or RG24-15M Replaces P/N 450-101  RG24-20 Replaces P/N 450-031	PMA Supplement No. 61 Issued 7/14/03 TSO Authorized: RG24-15, RG24-15M
Piper	(Cheyenne) PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-42, PA-42-720, PA-42-1000 (Replacing Ni-Cd battery)	Wilco (800) 767-7593	STC# SA00843WI	Options as follows: RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	PMA Supplement No. 80 Issued 12/02/05 TSO Authorized: RG-380E/44L, 44K, 60L, 60K
Polskie Zaklady Lotnicze Sp. Z.o.o.	PZL M28 05 (Replacing Ni-Cd battery)	Concorde Battery (800) 756-0303	TC# A56CE	RG-CIS25; 5-0263 (Kit, TS, TS-C10)	PMA Supplement No. 106 Issued 9/15/14 TSO Authorized: RG-CIS25
Revo Inc.	(Lake) LA-4, LA-4-200, Model 250 (S/N: 1-25 only)	Revo Inc. (Phone unknown)	FAA Design Approval	RG-35A or RG-35AXC	PMA Supplement No. 25 Issued 6/07/96
Robinson Helicopter	R-22	Robinson (310) 539-0508	TC# H10WE	RG-25XC	PMA Supplement No. 75 Issued 2/18/05
Robinson Helicopter	R-44	Robinson (310) 539-0508	TC# H11MN	RG-25XC (12V), RG24-15 (24V)	PMA Supplement No. 75 Issued 2/18/05
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (Replacing flooded lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40B or RG-380E/44	PMA Supplement No. 15 Issued 1/06/92 TSO Authorized: RG-380E/40B, /44
Sabreliner	265-40, -60, -65, -70, -80 (Replacing Ni-Cd battery)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-380E/44	PMA Supplement No. 36 Issued 4/20/98 TSO Authorized: RG-380E/44
Sabreliner	265-65 (Replacing Ni-Cd battery)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-206 (Emergency Battery)	PMA Supplement No. 36 Issued 4/20/98 TSO Authorized: RG-206
Short Brothers & Harland Ltd.	SD 3-30 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	PMA Supplement No. 29 Issued 1/17/97 TSO Authorized: RG-380E/44
Short Brothers & Harland Ltd.	SD 3-30 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126 (Emergency Battery)	PMA Supplement No. 29 Issued 1/17/97 TSO Authorized: RG-126
Short Brothers & Harland Ltd.	SD 3-60 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	PMA Supplement No. 28 Issued 1/17/97 Rev. 2/21/97 TSO Authorized: RG-380E/44
Short Brothers & Harland Ltd.	SD 3-60 (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126 (Emergency Battery)	PMA Supplement No. 28, Issued 01/17/97 Rev. 2/21/97 TSO Authorized: RG-126
Sikorsky	CH-54B	Helicopter Transp. (541) 754-2400	STC# SR01241SE	RG-390E	PMA Supplement No. 78 Issued 3/2/05 TSO Authorized: RG-390E
Sikorsky	S-76A (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR00091LA	RG-380E/40B	PMA Supplement No. 19 Issued 8/24/95 TSO Authorized: RG-380E/40B
Sikorsky	S-76B (Replacing Ni-Cd battery)	Concorde Battery (800) 757-0303	STC# SR03819AT	RG-390E	PMA Supplement No. 91 Issued 4/09/10 TSO Authorized: RG-390E
Sikorsky	S-76A, C, C+ (Replacing Ni-Cd battery)	Falcon Crest Av. (800) 833-5422	STC & STA# SR09050RC	RG-380E/44	PMA Supplement No. 22 Issued 01/23/96 TSO Authorized: RG-380E/44

<b>Manufacturer</b>	<b>Model &amp; Certificate Notes<sup>8</sup></b>	<b>Certificate Holder</b>	<b>Certificate Number (or FAA Design Approval)</b>	<b>Concorde Part Number<sup>7</sup></b>	<b>FAA Approval Type</b>
<b>Slingsby Aviation</b>	Firefly Models T67M260 & T67M260-T3A	Slingsby Aviation (011) (44) (1751) 432474	TC# A73EU Rev. 2 BA 17, Issue 6	RG24-11M	PMA Supplement No. 27 Issued 7/03/96
<b>Tamarack Helicopters</b>	Bell UH-1F, TH-1F, UH-1P (Replacing Ni-Cd battery)	Tamarack Heli. (406) 777-0144	STC# SR01349LA	RG-390E	PMA Supplement No. 53 Issued 3/26/03 TSO Authorized: RG-390E
<b>Textron Aviation</b>	See Beechcraft & Cessna				
<b>True Flight Holdings</b>	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B	Concorde Battery (800) 757-0303	STC# SA01250WI	RG-25 or RG-25XC (12V); RG24-11M or RG24-15M (24V)	PMA Supplement No. 71 Issued 6/04/04 TSO Authorized: RG24-15M
<b>Twin Commander</b>	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	PMA Supplement No. 15 Issued 1/06/91 TSO Authorized: RG-380E/44
<b>Univair</b>	415-C, 415-D, 415-CD (S/N 113 and up)	Univair (303) 375-8882	TC# A-718 Rev. 29, Issued 07/14/05	RG-25	PMA Supplement No. 79 Issued 11/23/05
<b>Univair</b>	Ercoupe: 415-E, 415-G, 415F-1 (All S/N's) Forney: F-1A (S/N 5715 – 5729)	Univair (303) 375-8882	TC# A-787 Rev. 33, Issued 07/14/05	RG-25	PMA Supplement No. 79 Issued 11/23/05
<b>Univair</b>	Forney: F-1A (S/N 5730 and up) Alon: A-2, A-2A; Mooney M-10	Univair (303) 375-8882	TC# A-787 Rev. 33, Issued 07/14/05	RG-25	PMA Supplement No. 79 Issued 11/23/05
<b>Univair</b>	Stinson: 108, 108-1, 108-2, 108-3, 108-5	Univair (303) 375-8882	TC# A-767 Rev. 27, Issued 07/14/05	RG-35A	PMA Supplement No. 79 Issued 11/23/05
<b>Viking Air Ltd</b>	DHC-6-1, -100, -200, -300 (Replacing Ni-Cd or lead-acid battery)	Concorde Battery (800) 757-0303	STC#SA03971AT	RG-380E/44 or RG-380E/60L; RG-300 (Aux.- Optional); 5-0455 (Aux. Mating Conn.); 4000 (Conn.- AN-3150 lead-acid replacement only)	PMA Supplement No. 101 Issued 8/20/12 Rev. 10/13/15 TSO Authorized: RG-380E/44, /60L; RG-300

**FAA TSO-C173 Authorizations**

Authorized per FAA TSO-C173 <sup>4</sup>

<b>Concorde Part number</b>	<b>Date of Approval</b>	<b>Concorde Part number</b>	<b>Date of Approval</b>
RG-42 and RG-42[ ]	May 27, 2011	RG-380E/46 and RG-380E/46[ ]	October 5, 2012
RG-47 and RG-47[ ]	July 1, 2010	RG-380E/46L and RG-380E/46L[ ]	October 5, 2012
RG-49 and RG-49[ ]	July 1, 2010	RG-380E/46LS and RG-380E/46LS[ ]	October 5, 2012
RG-121 Series	December 3, 2007	RG-380E/46K and RG-380E/46K[ ]	October 5, 2012
RG-122 Series	December 3, 2007	RG-380E/46KS and RG-380E/46KS[ ]	October 5, 2012
RG-125	July 31, 2008	RG-380E/60B and RG-380E/60B[ ]	November 4, 2010
RG-126	July 31, 2008	RG-380E/60K and RG-380E/60K[ ]	July 29, 2009
RG-128 Series	June 25, 2008	RG-380E/60KS and RG-380E/60KS[ ]	July 29, 2009
RG-129 Series	June 25, 2008	RG-380E/60L and RG-380E/60L[ ]	July 29, 2009
RG-131	January 3, 2008	RG-380E/60LS and RG-380E/60LS[ ]	July 29, 2009
RG-132	June 25, 2008	RG-390E and RG-390E[ ]	October 20, 2008
RG-145-1 and RG-145-1[ ]	November 5, 2010	RG-390ES and RG-390ES[ ]	October 20, 2008
RG-145-2 and RG-145-2[ ]	November 5, 2010	RG-390E/L and RG-390E/L[ ]	October 20, 2008
RG-206 and RG-206[ ]	July 1, 2010	RG-390E/LS and RG-390E/LS[ ]	October 20, 2008
RG-222 and RG-222[ ]	March 27, 2009	RG-390E/25 and RG-390E/25[ ]	December 14, 2011
RG-223 and RG-223[ ]	May 27, 2011	RG-390E/25S and RG-390E/25S[ ]	December 14, 2011
RG-224 and RG-224[ ]	May 27, 2011	RG-390E/25L and RG-390E/25L[ ]	December 14, 2011
RG-300 and RG-300[ ]	June 15, 2012	RG-390E/25LS and RG-390E/25LS[ ]	December 14, 2011
RG-325 and RG-325[ ]	February 29, 2012	RG-400E/13	March 6, 2008
RG-350 and RG-350[ ]	July 1, 2010	RG-407 and RG-407[ ]	March 29, 2011
RG-355 and RG-355[ ]	July 1, 2010	RG-427 and RG-427[ ]	March 12, 2013
RG-380E/40B and RG-380E/40B[ ]	September 9, 2008	RG-441 and RG-441[ ]	November 7, 2008
RG-380E/40K and RG-380E/40K[ ]	September 9, 2008	RG-442 and RG-442[ ]	November 7, 2008
RG-380E/40KS and RG-380E/40KS[ ]	September 9, 2008	RG-500 and RG-500[ ]	July 1, 2010
RG-380E/40L and RG-380E/40L[ ]	September 9, 2008	RG-600 and RG-600[ ]	July 1, 2010
RG-380E/40LS and RG-380E/40LS[ ]	September 9, 2008	RG-1835-1 and RG-1835-2	February 19, 2009
RG-380E/44 and RG-380E/44[ ]	August 15, 2008		
RG-380E/44K and RG-380E/44K[ ]	August 15, 2008		
RG-380E/44KS and RG-380E/44KS[ ]	August 15, 2008		
RG-380E/44L and RG-380E/44L[ ]	August 15, 2008		
RG-380E/44LS and RG-380E/44LS[ ]	August 15, 2008		
RG-380E/44KH and RG-380E/44KH[ ]	February 29, 2012		
RG-380E/44KSH and RG-380E/44KSH[ ]	February 29, 2012		
RG-380E/44LH and RG-380E/44LH[ ]	February 29, 2012		
RG-380E/44LSH and RG-380E/44LSH[ ]	February 29, 2012		

Authorized per FAA TSO-C173a <sup>5</sup>

Concorde Part number	Description	Date of Approval
HCU-6	LRU – Heater Control Unit Component	February 15, 2017
RG24-15	Battery	May 8, 2017
RG24-15M	Battery	May 8, 2017
RG24-16	Battery	May 8, 2017
RG-41/53	Battery	July 26, 2017
RG-150-1	Battery	April 29, 2014 Amended: March 17, 2016
B-150-1	Subassembly	April 29, 2014
BS-150-A	Subassembly	April 29, 2014
RG-150-2	Battery	April 29, 2014 Amended: March 17, 2016
MB-150-2	Subassembly	April 29, 2014
RG-150-1[-Y]	Battery	April 29, 2014 Amended: March 17, 2016
MB24-3.5-1	Subassembly	April 29, 2014
BS-150-C	Subassembly	April 29, 2014
RG-150-2[-Y]	Battery	April 29, 2014 Amended: March 17, 2016
RG-150-5	Battery	March 17, 2016
RG-150-6	Battery	March 17, 2016
RG-150-5[-Y]	Battery	March 17, 2016
RG-150-6[-Y]	Battery	March 17, 2016
MB24-3.5-2	Subassembly	April 29, 2014
RG-213	Battery	April 6, 2017
RG-235 and RG-235[ ]	Battery	August 27, 2014
RG-292-103	Battery	February 2, 2016
RG-330	Battery	December 6, 2016
RG-332-1 and RG-332-1[ ]	Battery	December 19, 2014
RG-332-2 and RG-332-2[ ]	Battery	December 19, 2014
RG-365 and RG-365[ ]	Battery	December 4, 2015
RG-380E/40D and RG-380E/40D[ ]	Battery	April 28, 2015
RG-380E/53L and RG-380E/53L[ ]	Battery	October 18, 2014
RG-380E/53LS and RG-380E/53LS[ ]	Battery	October 18, 2014
RG-380E/53K and RG-380E/53K[ ]	Battery	October 18, 2014
RG-380E/53KS and RG-380E/53KS[ ]	Battery	October 18, 2014
RG-380E/40GH-6	LRU - Battery Component	February 15, 2017
RG-380E/44GH-6	LRU - Battery Component	February 15, 2017
RG-380E/46GH-6	LRU - Battery Component	February 15, 2017
RG-380E/53GH-6	LRU - Battery Component	February 15, 2017
RG-380E/60GH-6	LRU - Battery Component	February 15, 2017
RG-380E/60KH and RG-380E/60KSH	Battery	April 29, 2013
RG-380E/60LH and RG-380E/60LSH	LRU - Battery Component	April 29, 2013
RG-390E/KH and RG-390E/KSH	LRU - Battery Component	April 29, 2013
RG-390E/LH and RG-390E/LSH	LRU - Battery Component	April 29, 2013
RG-390E/30 and RG-390E/30[ ]	Battery	November 20, 2015
RG-390E/30S and RG-390E/30S[ ]	Battery	November 20, 2015
RG-390E/30L and RG-390E/30L[ ]	Battery	November 20, 2015
RG-390E/30LS and RG-390E/30LS[ ]	Battery	November 20, 2015
RG-616 and RG-616[ ]	Battery	December 17, 2013
RG-624	Battery	December 7, 2016
RG-641 and RG-641[ ]	Battery	April 1, 2014
RG-CIS25 and RG-CIS25[ ]	Battery	December 3, 2014

Authorized per FAA TSO-C173a Incomplete <sup>6</sup>

Concorde Part number	Description	Date of Approval
HCU-1	LRU - Heater Control Unit Component	August 9, 2013
HCU-2	LRU - Heater Control Unit Component	August 9, 2013
HCU-3	LRU - Heater Control Unit Component	August 9, 2013
HCU-4	LRU - Heater Control Unit Component	August 9, 2013
HCU-7X	LRU - Heater Control Unit Component	August 9, 2013

## NOTES

Note 1 - Installations listed may require the battery purchase of an STC and/or STC Kit, aircraft modifications, etc. Contact the Concorde factory or the Certificate Holder for installation replacement details prior to battery purchase.

Note 2 - The products listed herein may be subject to export restrictions imposed by the United States. Export Licenses may be required. Customers are advised to contact Concorde for additional information on EAR or ITAR information as it pertains to these products.

Note 3 – It is highly recommended for the aircraft's original battery part number to be confirmed prior to choosing a replacement battery listed on this STC. The original number should be carefully matched to the Concorde battery listed as the replacement to avoid an error in battery selection. Please note for some replacement model numbers, there are certain Concorde models that are preferred based on fitment. Other batteries listed are for PMA information only. The original battery part number is typically available in the aircraft parts catalog.

Note 4 – The batteries listed under TSO were approved under Technical Standard Order C173 by the US Federal Aviation Administration which applies to permanently installed, rechargeable lead-acid batteries intended to provide power for aircraft equipment including emergency and standby systems and electrical power to start aircraft engines or auxiliary power units when required. Those installing a battery listed, on or in a specific type or class of aircraft, must determine that the aircraft installation conditions are within the TSO Standards. TSO articles must have a separate approval for installation in an aircraft. This article may be installed only according to 14 CFR part 43 or the applicable airworthiness requirements.

Note 5 - The conditions and tests required for TSO approval of this article are minimum performance standards. It is the responsibility of those installing the article on or within a specific type or class aircraft to determine that the aircraft installation conditions are within the TSO standards. TSO articles must have separate approval for installation in an aircraft. The article may be installed only if performed under 14 CFR Part 43 or the applicable airworthiness requirements.

Note 6 – The conditions and tests required for TSO approval of this article are minimum performance standards. It is the responsibility of those installing the article on or within a specific type or class aircraft to determine that the aircraft installation conditions are within the TSO standards. TSO articles must have separate approval for installation in an aircraft. The article may be installed only if performed under 14 CFR Part 43 or the applicable airworthiness requirements. The TSO-C173a is incomplete and its functions are listed in the installation Component Maintenance Manual.

Note 7 – Please note batteries listed herein are assumed to be main battery replacements unless otherwise indicated. STC documents may include model numbers prefixed "CB". The CB series has been discontinued and batteries from that product line have been removed from the Eligibility List. Even if removed, they remain legal options if still available in the field.

Note 8 – Please contact Concorde Customer Service or the approval holder for installation details prior to making a battery or STC Kit purchase. Please also refer to aircraft eligibility information published at [www.concordebattery.com](http://www.concordebattery.com).